


- See page 6 for Metric Conversions
- See page 7 for Taper Dimensions


SPADE ELECTRODES




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only




Bent Dimensions for Reference Only



Bent Dimensions for Reference Only



Bent Dimensions for Reference Only



*Optional material available on special order: RWMA CLASS 1 and CLASS 3